

LineageOS 15.1 for HTC M8S

<https://forum.xda-developers.com/htc-one-m8/one-m8s-general/rom-lineageos-htc-one-m8s-m8qlul-t3805704>

Versions

- 20 June 2018
 - Fixed headphones microphone
- 26 July 2018
 - July Android Security updates
 - Kernel updated from tag 3.10.49 to tag 3.10.108
 - Bluetooth now recognises the correct bt address
 - Use low-latency as primary output for notifications and ringtone
 - Switched SELinux to enforcing
 - When usb composition is on “charge only” adb works
 - Enabled audio offloading
 - Added the option to disable Double Tap to wake gesture
 - Added option to unlock phone with a gesture (you can find it under gestures tab)
 - Used newer WiFi configuration files (hope that fixes WiFi problems)
 - The name “HTC One M8s” is shown to your pc when connected instead of “Android Phone”
- 18 October 2018
 - August/September/October ASB merged
 - Use sdFAT instead of exFAT
 - Reduce GPS fix time
 - Increased speaker volume
 - Increased microphone volume
 - Increased upper earpiece volume when in-call
 - Enabled HDR
 - Fixed wakelock

Hello all, I just uploaded the new build in the server. Some words about some changes.

- 1) GPS fix time dramatically reduced to 0-5 seconds.
- 2) HDR is enabled in this build because it is kinda fixed. I need some feedback on this. When I take a picture with HDR enabled it seems that the picture is overexposed. This is currently Work In Progress, any feedback is much appreciated.
- 3) A terrible wakelock existed in previous build which caused the battery to drain fast when Mobile Data were enabled. This is fixed in this build.
- 4) From this build the ROM will not be pre-rooted. You have to either flash the su add-on from <https://download.lineageos.org/extras> or flash Magisk.
- 5) Lastly, I increased the volume in various things. I had seen some reports that the mic reception was low so I decided to increase some volumes. Please consider leaving a feedback.

- 26 October 2018
 - Instagram videos fixed

Installation

- Launcher: Googleonw or Trebuchet - better is to install **Nova Launcher**
- External SD card only to move files or extend internal memory (will be erased)
- Install weather provider:

Long GPS Fix

It looks like AGPS is not working

```
XTRA_SERVER_1=http://xtra1.gpsonextra.net/xtra.bin  
XTRA_SERVER_2=http://xtra2.gpsonextra.net/xtra.bin  
XTRA_SERVER_3=http://xtra3.gpsonextra.net/xtra.bin  
SUPL_HOST=supl.google.com  
SUPL_PORT=7276
```

```
mount -o rw,remount /system  
vim /etc/gps.conf
```

```
#XTRA_SERVER_1=http://xtra1.gpsonextra.net/xtra.bin  
#XTRA_SERVER_2=http://xtra2.gpsonextra.net/xtra.bin  
#XTRA_SERVER_3=http://xtra3.gpsonextra.net/xtra.bini  
  
XTRA_SERVER_1=https://xtrapath1.izatcloud.net/xtra3grc.bin  
XTRA_SERVER_2=https://xtrapath2.izatcloud.net/xtra3grc.bin  
XTRA_SERVER_3=https://xtrapath3.izatcloud.net/xtra3grc.bin  
  
NTP_SERVER=europe.pool.ntp.org  
  
SUPL_HOST=supl.google.com  
SUPL_PORT=7276
```

```
mount -o ro,remount /system
```

Status bar icons

remove root # icon

```
settings get secure icon_blacklist  
rotate,headset
```

```
settings put secure icon_blacklist rotate,headset,su  
reboot
```

enable screenshot power menu

Setting>Buttons>Power menu>. Select Screenshot

Wifi problems

```
iw wlan0 scan | grep SSID

dumpsys wifi
dumpsys wifiscanner

service list

am stop-service wificond
am start-service wificond
```

```
dumpsys wifiscanner
...
Latest scan results:
    BSSID          Frequency   RSSI   Age(sec)   SSID
Flags
    xx:xx:xx:xx:xx:50      2452     -61     0.000  abcdef-WIFI
[WEP] [ESS]
    xx:xx:xx:xx:xx:96      2472     -66     0.000  HUAWEI-B315-8796
[WPA2-PSK-CCMP] [ESS]
    xx:xx:xx:xx:xx:d0      5220     -75     0.000  abcdef-WIFI
[WEP] [ESS]
    xx:xx:xx:xx:xx:94      2437     -79     0.000  PLAY-ONLINE-6047
[WPA2-PSK-CCMP+TKIP] [WPA-PSK-CCMP+TKIP] [ESS]
    xx:xx:xx:xx:xx:22      2437     -90     0.000  ABCD_PT_23
[WPA2-PSK-TKIP] [ESS]
```

```
Latest native scan results:
    BSSID          Frequency   RSSI   Age(sec)   SSID
Flags
    xx:xx:xx:xx:xx:13      2412     -70    >1000.0  robofi
[WPA2-PSK-CCMP] [ESS]
    xx:xx:xx:xx:xx:96      2472     -66     0.000  HUAWEI-B315-8796
[WPA2-PSK-CCMP] [ESS]
    xx:xx:xx:xx:xx:58      2462     -65    >1000.0  robofi
[WPA2-PSK-CCMP] [ESS]
    xx:xx:xx:xx:xx:50      2452     -61     0.000  abcdef-WIFI
[WEP] [ESS]
    xx:xx:xx:xx:xx:94      2437     -79     0.000  PLAY-ONLINE-6047
[WPA2-PSK-CCMP+TKIP] [WPA-PSK-CCMP+TKIP] [ESS]
    xx:xx:xx:xx:xx:d0      5220     -75     0.000  abcdef-WIFI
[WEP] [ESS]
    xx:xx:xx:xx:xx:1b      2412     -66    >1000.0  DIRECT-NRC43x Series
```

[WPA2-PSK-CCMP] [ESS] [WPS]					
xx:xx:xx:xx:xx:b3	2412	-75	>1000.0	HUAWEI P9 lite 2017	
[WPA2-PSK-CCMP] [ESS]					
xx:xx:xx:xx:xx:22	2437	-90	0.000	ABCD_PT_23	
[WPA2-PSK-TKIP] [ESS]					
xx:xx:xx:xx:xx:e3	2462	-89	>1000.0	Honor 8	
[WPA2-PSK-CCMP] [ESS]					

problem:

<https://discuss.96boards.org/t/wifi-does-not-connect-to-the-router-phone-hotspot-with-aosp-prebuilt-image/5344> kernel patch <https://patchwork.kernel.org/patch/10547433/>

From:
<https://niziak.spox.org/wiki/> - **niziak.spox.org**



Permanent link:
<https://niziak.spox.org/wiki/android:lineage>

Last update: **2019/02/01 07:20**