

1705-Slot X Drive Array - Please replace Cache Module Super-Cap. Caching will be enabled once Super-Cap has been replaced and charged.

[How to: change a HP Proliant DL380p Gen 8 raid array capacitor/battery](#)

From:
<https://niziak.spox.org/wiki/> - **niziak.spox.org**

Permanent link:
<https://niziak.spox.org/wiki/hw:server:proliant380eg8:issues>

Last update: **2023/08/04 09:39**

