

<https://github.com/jziolkowski/tdm>

issues

OTA: upload buffer miscompare

Too small free flash space. Try to upload very minimal binary or upload .gz compressed binary.

From:

<https://niziak.spox.org/wiki/> - **niziak.spox.org**

Permanent link:

https://niziak.spox.org/wiki/home_automation:esp8266:tasmota

Last update: **2021/01/21 21:11**

