

BCM20702A0 based USB dongles

- ASUSTek Computer, Inc. Broadcom BCM20702A0 Bluetooth
- ASUS Bt-400 0b05:17cd

Firmware

```
[ 489.427780] usb 3-7: new full-speed USB device number 9 using xhci_hcd
[ 489.450343] usb 3-7: New USB device found, idVendor=0b05, idProduct=17cb,
bcdDevice= 1.12
[ 489.450345] usb 3-7: New USB device strings: Mfr=1, Product=2,
SerialNumber=3
[ 489.450346] usb 3-7: Product: BCM20702A0
[ 489.450347] usb 3-7: Manufacturer: Broadcom Corp
[ 489.450348] usb 3-7: SerialNumber: 5CF3708AD929
[ 489.561988] Bluetooth: hci1: BCM: chip id 63
[ 489.562988] Bluetooth: hci1: BCM: features 0x07
[ 489.578996] Bluetooth: hci1: BCM20702A
[ 489.580014] Bluetooth: hci1: BCM20702A1 (001.002.014) build 0000
[ 489.587827] bluetooth hci1: firmware: failed to load
brcm/BCM20702A1-0b05-17cb.hcd (-2)
[ 489.587828] firmware_class: See https://wiki.debian.org/Firmware for
information about missing firmware
[ 489.587830] bluetooth hci1: Direct firmware load for
brcm/BCM20702A1-0b05-17cb.hcd failed with error -2
[ 489.587831] Bluetooth: hci1: BCM: Patch brcm/BCM20702A1-0b05-17cb.hcd not
found
```

Download [BCM20702A1-0b05-17cb.hcd](#) and put into /lib/firmware/brcm

From:
<https://niziak.spox.org/wiki/> - **niziak.spox.org**

Permanent link:
<https://niziak.spox.org/wiki/linux:bluetooth:bcm20702a1>

Last update: **2018/08/24 11:28**

